




Assembly Instruction (WLF-C11)




Parts List Open the hardware check all parts QTY, thanks



A x 2



B x 2




C x 1



D x 8




E x 4




F x 1

Step 1 ! The screw must be loose to finish



Step 2 ! The screw must be loose to finish



Tighten all screws to finish